

## Technical Bulletin N°07

REFERENCE	BT_2017_FR20_07_UK
DATE	2017-05-17
SUBJECT	Water-Engine oil Temperature sensors connectors evolution + AIM Software + Front wing bracket evolution
PARTS	Water-Engine Oil Temperature sensors – Front Wing bracket

### 1. Water-Oil Temperature sensors connectors evolution - OPTIONAL

Renault Sport Racing offer you the possibility to update water-oil temperature sensors connectors from the OEM standard fitting to a Superseal 2 ways fitting. This evolution is free of charge for Eurocup Formula Renault team.

As water temperature is the most important sensor (no closed loop in the mapping for Oil temperature), water connectors will be update in priority.

Please note that this evolution can only be made if you use remote water/oil temperature sensor reference 77 11 166 957. If you use the standard sensor reference 77 11 162 634, this evolution can't be carried out.

Spare parts will be update soon and only remote connectors with Superseal 2 ways will be available for remote sensor. Standard sensor will still be available.



### 2. Software to recover corrupt video (AIM SmartyCam)

If it appears that some videos can't be opened because they are corrupt. If you faced this problem, you can try to recover this video using the software available on the extranet:

<https://sites.google.com/a/renault-sport.com/formule-renault-2-0-fr/logiciels/aim-smarty-cam>

### 3. Front Wing bracket evolution

A new shape of front wing bracket will be introduced reference 77 11 166 956, in order to reduce crashbox damage during crash. Backward shape have now a less aggressive design compare to the previous version (reference 77 11 167 720), and the hole disappear to avoid any cracks. Both reference are allowed.



Renault Sport Racing  
Vehicle Design Department